



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 29, 2008

Reviewed _____

Mine Name: Travertine 1	Permit Number: M0230042
Operator Name: BEG Resources	Inspection Date: March 12, 2008
Inspector(s): L Heppler, T Munson	Time: 10:15 am
Other Participants: None	Mine Status: INA

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 06-18-2005 **Bond Amount:** \$15,100 **Permit fee** is delinquent – need to pay fee

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Nothing has been done to the site since last inspection

Conclusions and Recommendations: The reclaimed area does not meet this revegetation success standard, and the area is not expect to meet this standard without remedial work, reseeding is needed. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:pb

cc: Gary Burningham – BEG Resources, Inc.

Jerry Mansfield – BLM

Attach - GIS

O:\M023-Juab\M0230042-Begtravertine\inspections\Insp_BEG_03-12-08.doc

0001